

Furnace Interior after Oxide Removal



August 12, 2002

Part II - Slide 1

Furnace Just Prior to Slag Removal



View of Tray and Stand “Slag” Remains after Oxide Removal (Slag lifted from Furnace Floor with Scoop)



August 12, 2002

Part II - Slide 3

Slag Piece Removed from Furnace #2



Majority of Slag Removed in One Piece



August 12, 2002

Part II - Slide 5

Close-up of Corner of Slag



Slag Close-up. Tray outline can be seen as well as location of stand cross members



Close-up of Slag



August 12, 2002

Furnace After Large Piece of Slag Removed



August 12, 2002

Part II - Slide 9

Furnace After Slag Removal - Partial View of West Furnace Elements



August 12, 2002

Part II - Slide 1

0

Last Material Swept From Furnace & Samples



August 12, 2002

Part II - Slide 1

1

Furnace Interior After Final Sweep Out



August 12, 2002

Part II - Slide 1

2